



www.litprints.co.uk

Dear Customer

Thank you for your purchase and interest in our OO Gauge OLE Frames. It has been designed to fit together with ease and be wired for a more dense / busy look. Please review the features and see the guide on how to setup the OLE Frames.

Contents:




Cantilever arms x6 Mast base x6 H Frame Masts x6 H Frame x3 Supports x6 Cantilever mounts x6

ASSEMBLY INSTRUCTIONS.


1) Take H Frame and Mount Cantilever Mounts to the frame as shown in picture below: (use the notches provided in the H-Frame then slide the Cantilever mounts into place) Be careful not to crush them.



2) Mount and glue H Frame masts, supports and base as shown in images above and below:



3) Finally glue the Cantilever Arms to the Cantilever Mounts.



Please note do not get glue between the Cantilever Mounts and the H-Frame, they will not be adjustable afterwards. Adjusting the arms is useful for track corners or splits. Use a hot pin to open up wire holes.

It would be greatly appreciated if you left feedback, this will allow LitPrints to grow and invent new products to improve life quality or aesthetics.