



[www.litprints.co.uk](http://www.litprints.co.uk)

## Dear Customer

Thank you for your purchase and interest in our OO Gauge OLE Frames. It has been designed to fit together with ease and be wired for a more dense / busy look. Please review the features and see the guide on how to setup the OLE Frames.

Contents:



Cantilever arms x9 Mast base x6 H Frame Masts x6 H Frame x3 Supports x6 Cantilever mounts x9

## ASSEMBLY INSTRUCTIONS.


1) Take H Frame and Mount Cantilever Mounts to the frame as shown in picture below: (use the notches provided in the H-Frame then slide the Cantilever mounts into place) Be careful not to crush them.



2) Mount and glue H Frame masts, supports and base as shown in images above and below:



3) Finally glue the Cantilever Arms to the Cantilever Mounts.



*Please note do not get glue between the Cantilever Mounts and the H-Frame, they will not be adjustable afterwards. Adjusting the arms is useful for track corners or splits. Use a hot pin to open up wire holes.*

*It would be greatly appreciated if you left feedback, this will allow LitPrints to grow and invent new products to improve life quality or aesthetics.*