

## www.litprints.co.uk

## Contents:

Mast x2



Thank you for your purchase and interest in our OO Gauge OLE Frames.

It has been designed to fit together with ease and be wired for a more dense / busy look.

Please review the features and see the guide on how to setup the OLE Frames.

> 1) 2)











Arms x2




Auto transformer wire mount

x2







Add the auto transformer wire mount as shown

in on the right. (This is optional). Then add the


weight to the wire clamp as shown in the





Wire clamp x2

Weight x2



Please note; This product is not designed to be adjustable afterwards. It is a 'position once' OLE frame.





Mount and glue H Frame mast and base as shown in image on left.

Add the insulators to the arms as shown below.





It would be greatly appicated if you left feedback, this will allow LitPrints to grow and invent new products to improve life quality or asthetics.